Village of New Maryland

WATER SERVICE NOTICE
SPRINGWATER SUBDIVISION



We experienced an issue with the chlorinator at our Springwater Reservoir, which required us to shut it down on Saturday morning.

As a result, Springwater Subdivision is currently being supplied by our Applewood system until we can get the issue corrected.

Residents may notice:

- Lower-than-normal water pressure.
- A slight chlorine smell in the water. This is normal and safe for drinking water levels.

If you experience extremely low water pressure or have any concerns, please contact our office at 506-451-8508.

We apologize for any inconvenience and appreciate your patience and understanding while we work to resolve the issue.